


## Database of Steel Transformation Diagrams v. 4.0



### Features

Number of diagrams: 6032  
Number of CCT diagrams: 3597  
Number of TTT diagrams: 2142  
Number of TTP diagrams: 141  
Number of TTS diagrams: 93  
Keyword searching

Calculated diagrams: 103  
Cast irons: 173  
Cold work tool steels: 312  
DIN steel index: 1550  
Embrittlement diagrams: 29  
High speed steels: 88  
Hot work tool steels: 100  
Molybdenum steels: 460  
PM (Powder Metallurgy) steels: 40  
Stainless steels: 366  
Structural steels: 2060  
Tools steels: 1063  
Welding steels: 509  
White cast irons: 109  
Wr.Nr. (Mat.No.) steel index: 2272  
and other steels from producers

### System requirements

#### For the computers with the Windows OS:

Microsoft Windows® 95, 98, ME, 2000, XP, Vista, Windows 7, 8 and 10,  
RAM: Recommended 1 Gb or greater,  
Hard disk free space: 700 Mb,  
Recommended screen resolution: 800 x 600 pixels or higher,  
Browser Microsoft Internet Explorer 6 or higher.

#### For the computers with the Mac OS:

Mac OS X (Jaguar, Leopard, Lion, Mountain Lion, Panther, Snow Leopard, Tiger, Mavericks, Yosemite, Sierra Nevada),  
RAM: Recommended 1 Gb or greater,  
Hard disk free space: 700 Mb,  
Recommended screen resolution: 800 x 600 pixels or higher,  
Browser Safari, Mozilla for the OS X.

#### For the computers with the Linux OS:

OpenSuse, Debian, Slackware, Fedora, Gentoo, Ubuntu,  
RAM: Recommended 1 Gb RAM or greater,  
Hard disk free space: 700 Mb,  
Recommended screen resolution: 800 x 600 pixels or higher,  
Browser Mozilla, Safari or any other browser which support the Java script.

### Price

400.00 US \$ (Single user, one computer)  
1,200.00 US \$ (Server version, Intranet)

### Steel Data

Email: [info@steeldata.info](mailto:info@steeldata.info)  
<http://www.steeldata.info>