


Database of Steel Transformation Diagrams v. 3.0



Features

Number of diagrams: 5063
Number of CCT diagrams: 3175
Number of TTT diagrams: 1673
Number of TTP diagrams: 124
Number of TTS diagrams: 91
Keyword searching

Calculated diagrams: 303
Cast irons: 152
Cold work tool steels: 285
DIN steel index: 2581
Embrittlement diagrams: 29
High speed steels: 88
Hot work tool steels: 112
Molybdenum steels: 183
PM (Powder Metallurgy) steels: 91
Stainless steels: 315
Structural steels: 1716
Tools steels: 876
Welding steels: 374
White cast irons: 109
Wr.Nr. (Mat.No.) steel index: 2127
and other steels from producers

System requirements

For the computers with the Windows OS:

Microsoft Windows® 95, 98, ME, 2000, XP, Vista, Windows 7, 8 and 8.1,
RAM: Recommended 1 Gb or greater,
Hard disk free space: 600 Mb,
Recommended screen resolution: 800 x 600 pixels or higher,
Browser Microsoft Internet Explorer 6 or higher.

For the computers with the Mac OS:

Mac OS X (Jaguar, Leopard, Lion, Mountain Lion, Panther, Snow Leopard, Tiger, Mavericks, Yosemite),
RAM: Recommended 1 Gb or greater,
Hard disk free space: 600 Mb,
Recommended screen resolution: 800 x 600 pixels or higher,
Browser Safari, Mozilla for the OS X.

For the computers with the Linux OS:

OpenSuse, Debian, Slackware, Fedora, Gentoo, Ubuntu,
RAM: Recommended 1 Gb RAM or greater,
Hard disk free space: 600 Mb,
Recommended screen resolution: 800 x 600 pixels or higher,
Browser Mozilla, Safari or any other browser which support the Java script.

Price

400.00 US \$

Steel Data

Email: info@steeldata.info
<http://www.steeldata.info>